(http://www1.nyc.gov/)

OpenRecords

11/17/18

Log Out (/auth/logout)

open RECORDS

(/)

FOIL-2018-826-02952 @

Title:

Public

Private

Flood, catch basin & water main records at 48th St & 37th Ave Queens on 7/15/18 - 7/19/16

Description:

Work was being done at the corner of 37th Avenue and 48th Street in Queens on July 19th pertaining to flood events that occured between the 15th and 18th of July 2018. Looking for information on the job that took place on July 19, 2018 at that corner and any related records.

Please provide records for all complaints, work orders, jobs info and completion info of work that took place to catch basings on 48th Street and 37th Avenue since July 15th.

When was the work order placed? What was being worked on? Why was the request made to for work on those catch basins/sewer/water main.

Agency Request Summary:

Public F

Private

Click here to edit the agency request summary

This requester can be contacted by:

Email

In Progress

(http://www1.nyc.gov/)

OpenRecords

Log Out (/auth/logout)

4)pen RECORDS

(/)

FOIL-2018-826-02953 @

Title: Public Private

Flood, catch basin & water main records at 48th St & 37th Ave Queens on 7/15/18 - 7/19/18

Description:

Work was being done at the corner of 37th Avenue and 48th Street in Queens on July 19th pertaining to flood events that occured between the 15th and 18th of July 2018. Looking for information on the job that took place on July 19, 2018 at that corner and any related records.

Please provide records for all complaints, work orders, jobs info and completion info of work that took place to catch basings on 48th Street and 37th Avenue since July 15th.

When was the work order placed? What was being worked on? Why was the request made to for work on those catch basins/sewer/water main.

Agency Request Summary:

Public Private

Click here to edit the agency request summary

This requester can be contacted by:

Email

In Progress



Report Date: Thursday, May 02, 2019

Page 1 of 2

Service#

186549435

Problem:

SZZ

OTHER SEWER PROBLEM (USE COMMENTS)

Address(I):

Cross Street:

37 AVE

APT:

48 ST

ZIP: 11101

Pct: 114

Borough: QUEENS

Compass Direction:

N

Block:

SegmentID:

CMBD: 401

Sub-Area: 401 QUEENS COMMUNITY BOARD 1

Location:

Area:

Building ID:

Lot:

of Calls:

4

QUEENS

District:

Parcel:

Call Date:

04-20-2018 08:11 AM

Taken By:

N/A 4767 Occurred Date: N/A MORALES, JANET

Request Date:

04-20-2018 08:11 AM

Responsibility:

SQN

SEWER MAINTENANCE-QUEENS N.

Source:

ECC- EMERGENCY COMMAND CENTER

Scheduled Date:

N/A

Start Date: 04-19-2018 11:00 AM

Priority:

Z- DEFAULT PRIORITY

Inspector:

4377

MARINELLI, JOSEPH

Inspection Date:

04-19-2018 01:15 PM

Resolution Code:

Incident Date: 04-19-2018 11:00 AM

Resolution Date: Due Date:

N/A N/A

Primary Caller Information

Customer Contact Requested: N

Title:

MARINELLI

Reference#

N/A

CallerKey: 186549435

Last Name: First Name, MI:

JOSEPH

Evening Phone:

N/A

N/A

Address:

Cell Phone:

(718)353-6904

City/State/Zip:

SUPERVISOR SQN

Day Phone:

Call Date: 04-20-2018 08:11 AM

Caller Comments:

INSPECT AREA

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	04-19-2018	04-19-2018	4377-MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop. Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 8:44:33 AM

Work Order	Priority	Activity	Problem	Unit-ID	Asset	Initiated	Completed	Source	Maint-Type
844166945		SA23		CB431602	STIN	04-09-2018	N/A		
844166947		SA220		CB431602	STIN	04-19-2018	N/A	di .	
844166949		SMPC		CB431601	STIN	04-19-2018	04-19-2018	FOPS	
844166954	-	SA25		CB431601	STIN	04-19-2018	07-19-2018		
844166960		SA220		CB431606	STIN	04-19-2018	N/A	2:	





Report Date:Thursday, May 02, 2019

Page 2 of 2

Work Order	Priority	Activity	Problem	Unit-ID	Asset	Initiated	Completed	Source	Maint-Type
844250902		WA12I				12-11-2018	N/A		



Block:

Non-Completed Storm Inlet Work Order

Report Date: Thursday, May 02, 2019

Page 1 of 2

Work Order# 844166945 Activity: SA23 REPAIR BASIN-MINOR

Address:

37 AVE

Pct: 114

Zip: 11101

Cross Street:

48 ST

Compass Direction:

Ν

Borough: QUEENS

Building ID:

Lot:

CMBD: 401

Map# QI137

Storm Inlet ID:

CB431602

Address:

48 ST

Qualifier:

ON

15 FROM 48TH ST

48TH ST/43RD ST

Area: Location : 4

4

Sub-Area: 401 QUEENS COMMUNITY BOARD 1

Asset Location Comments: ON

15 FROM 48TH ST

48TH ST/43RD ST

ON

15 FROM 48TH ST 48TH ST/43RD ST

Initiated By:

4377

MARINELLI, JOSEPH

Initiated: 04-09-2018 11:00 AM

Scheduled: N/A

Assigned To:

12241

RYAN, RICHARD

Service# 186549435

District: 844166945

Due: N/A

Authorization:

1177

ANELLO, THOMAS

Crew:

Maint Type:

Priority:

Problem:

Project: Source: Permit#

Completed: N/A

Out of Service: N

Potential Service Request: N

WO Responsibility:

WRQ

QUEENS REPAIRS

WO Comments:

Caller Comments for SR #: 186549435.....INSPECT AREA

	20/21/02/09/21/02/09/21/03/09/21/03/21/03/21/03/21/03/21/03/21/03/21/03/21/03/21/03/21/03/21/03/21/03/21/03/2	THE RESIDENCE OF THE PROPERTY OF THE PARTY O	PCSS CRICERON CONTROL SECUNDARION CONTROL CONT	Security from the first tree tree and the first tree tree tree tree tree tree tree t
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	04-19-2018	04-19-2018	4377- MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop Inspection down with P. Saurin (engineer). Input By: LINDA BUSH or 7/3/2018 9:25:59 AM



Report Date: Thursday, May 02, 2019

There are no user logs for this work order

Primary Caller Information

Primary Caller:

MARINELLI, JOSEPH

Address:

SUPERVISOR SQN

Day Phone:

(718)353-6904

Comments:

INSPECT AREA

Custlog Histo	Custlog History								
Log Type	Log Started	Log Ended	Log By	Comments					
INITIAL	04-19-2018	04-19-2018	4377-MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop. Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 8:44:33 AM					

Activity Safety Messages:

There are no Safety Messages for this asset's Activity Code

Asset Safety Messages:



Non-Completed Storm Inlet Work Order

Report Date: Thursday, May 02, 2019

Page 1 of 2

Work Order#

844166947

Activity: SA220

INSTALL HOOD & HANGER ON OPEN CURB PIECE

Address:

37 AVE

Pct: 114

Zip: 11101

Cross Street:

48 ST

Compass Direction:

N

Borough: QUEENS

Building ID:

Block:

Lot:

CMBD: 401

Map# QI137

Storm Inlet ID:

CB431602

Address:

48 ST

Qualifier:

ON

15 FROM 48TH ST

48TH ST/43RD ST

Area:

Sub-Area: 401 QUEENS COMMUNITY BOARD 1

Location:

Asset Location Comments: ON15 FROM 48TH ST48TH

ST/43RD STON15 FROM 48TH ST48TH ST/43RD ST

District: 844166947

Initiated By: Assigned To: 4377 1916 MARINELLI, JOSEPH

CHARLES-RAMIREZ, JOSE

Initiated: 04-19-2018 11:00 AM Service# 186549435

Scheduled: N/A

Due: N/A

Authorization:

1177

ANELLO, THOMAS

Crew:

Maint Type:

Priority:

Problem:

Project:

Source:

Permit#

Completed: N/A

Out of Service: N

Potential Service Request: N

WO Responsibility:

WRQ

QUEENS REPAIRS

WO Comments:

Caller Comments for SR #: 186549435.....INSPECT AREA

Work Order Log History								
Log Type	Log Started	Log Ended	Log By	Comments				
INITIAL	04-19-2018	04-19-2018	4377- MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop. Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 9:28:54 AM				

There are no user logs for this work order

P	ri	m	a	гy	Ca	H	er.	In	f٠)T	m	a	ti	0	n	

Primary Caller:

MARINELLI, JOSEPH

Call Date: 04-20-2018 08:11 AM



Report Date: Thursday, May 02, 2019

Page 2 of 2

Address:

SUPERVISOR SQN

Day Phone:

(718)353-6904

Comments:

INSPECT AREA

Custiog Histor	r y			
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	04-19-2018	04-19-2018	4377-MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop. Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 8:44:33 AM

Activity Safety Messages:

There are no Safety Messages for this asset's Activity Code

Asset Safety Messages:



Completed Storm Inlet Work Order

Report Date: Thursday, May 02, 2019

Page 1 of 2

Zip: 11101

Work Order# 844166949 Activity: SMPC **POLE CAMERA** Address: 37 AVE Pct: 114

48 ST Cross Street:

Borough: QUEENS Compass Direction: Ν

Block: Building ID: Lot: CMBD: 401

Storm Inlet ID: CB431601

20 FROM 37TH AV

Address: 48 ST

Qualifier: ON Map# QI137 20 FROM 37TH AV

37TH AV/NORTHERN BL

Sub-Area: 401 QUEENS COMMUNITY BOARD 1 Area:

Location: Asset Location Comments: ON District: 844166949

20 FROM 37TH AV 37TH AV/NORTHERN BL

37TH AV/NORTHERN BL Initiated By: 4377 MARINELLI, JOSEPH Initiated: 04-19-2018 11:00 AM Scheduled: N/A

Assigned To: 5893 SALERNI, ROBERTO Service# 186549435 Due: N/A

Authorization: 1177 ANELLO, THOMAS

Crew: S1 SEWER-1 LABORER Maint Type:

Priority: Problem: Permit#

Project: Completed: 04-19-2018 01:15 PM

FOPS FIELD OPERATIONS Source: Out of Service: N

Potential Service Request: N

WO Responsibility: SQN SEWER MAINTENANCE-QUEENS N.

WO Comments: Caller Comments for SR #: 186549435.....INSPECT AREA

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	04-19-2018	04-19-2018	4377- MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop. Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 9:31:17 AM





Report Date: Thursday, May 02, 2019

There are no user logs for this work order

Primary Caller Information

Primary Caller:

MARINELLI, JOSEPH

Address:

SUPERVISOR SQN

Day Phone:

(718)353-6904

Comments:

INSPECT AREA

Custlog History								
Log Type	Type Log Started Log Ended Log By		Log By	Comments				
INITIAL	04-19-2018	04-19-2018	4377-MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop. Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 8:44:33 AM				

Activity Safety Messages:

There are no Safety Messages for this asset's Activity Code

Asset Safety Messages:



Completed Storm Inlet Work Order

Report Date: Thursday, May 02, 2019

Page 1 of 2

Activity: SA25 REPAIR CONNECTION Work Order# 844166954 Address: 37 AVE Pct: 114 Zip: 11101 48 ST Cross Street: **Borough: QUEENS** Compass Direction: Ν Block: Lot: CMBD: 401 Building ID: CB431601 Storm Inlet ID: 48 ST Address: ON Qualifier: Map# QI137 20 FROM 37TH AV 37TH AV/NORTHERN BL Sub-Area: 401 QUEENS COMMUNITY BOARD 1 Area: Asset Location Comments: ON Location: District: 844166954 20 FROM 37TH AV 37TH AV/NORTHERN BL ON 20 FROM 37TH AV 37TH AV/NORTHERN BL 4377 Initiated By: MARINELLI, JOSEPH Initiated: 04-19-2018 11:00 AM Scheduled: N/A Due: N/A Assigned To: 1916 CHARLES-RAMIREZ, JOSE Service# 186549435 Authorization: 1177 ANELLO, THOMAS Crew: Maint Type: Priority: Permit# Problem: Completed: 07-19-2018 02:00 PM Project: Source: Out of Service: N Potential Service Request: N WO Responsibility: WRQ QUEENS REPAIRS

WO Comments:

Caller Comments for SR #: 186549435.....INSPECT AREA

Work Order Log History									
Log Type	Log Started	Log Ended	Log By	Comments					
INITIAL	04-19-2018	04-19-2018	4377- MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop. Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 9:34:22 AM					



Report Date:Thursday, May 02, 2019

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-19-2018	07-19-2018		37 AVE AND 48 STSUPV MILLER / CEW CIVITANO/WYATT/WAGNER R 904/922/551 BACKHOE JOHNNYAO/L, SET UP W/Z. B/O 6X10 OVER SEWER BREAK 1' DOWN. FOUND ELECTRIC DUCTS RUNNING DIAGANALLY THROUGH EXCAVATION. DUG DOWN BY HAND AND EXPOSED CONNECTION. MIXED 2 BAGS OF CEMENT AND INSTALLED 12' OF PIPE W/3 COLLARS. B/F, TAMPED AND BLACKTOPPED. Input By: MOIRA LYN FABLE on 12/11/2018 7:41:44 PM
FOLLOWUP	07-20-2018	07-20-2018		103 ST AND MARTENSE AVESUPV QUINONES / CREW ANZELONE/RUSSELLO/ROSENVEIG TR 913/810DROP 25 BAGS OF BLACKTOP. TAMPED TO GRADE, REMOVED DEBRIS. LEFT AREA CLEAN AND SAFE. N/F/A Input By: MOIRA LYN FABLE on 12/11/2018 8:10:17

There are no user logs for this work order

Primary Caller Information

Primary Caller:

MARINELLI, JOSEPH

SUPERVISOR SQN

Address: Day Phone:

(718)353-6904

Comments:

INSPECT AREA

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	04-19-2018	04-19-2018	4377-MARINELLI, JOSEPH	Marinelli/Salemi veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 8:44:33 AM

Activity Safety Messages:

There are no Safety Messages for this asset's Activity Code

Asset Safety Messages:



0 Non-Completed Storm Inlet Work Order

Report Date: Thursday, May 02, 2019

Page 1 of 2

Work Order#

844166960

Activity: SA220

INSTALL HOOD & HANGER ON OPEN CURB PIECE

Address:

37 AVE

Pct: 114

Zip: 11101

Cross Street:

48 ST

Compass Direction:

Ν

Borough: QUEENS

Building ID:

Block:

Lot:

CMBD: 401

Map# QI137

Storm Inlet ID:

CB431606

Address:

48 ST

Qualifier:

ON

40 FROM 37TH AV

BARNETT AV/37TH AV

Area:

4

4

Sub-Area: 401 QUEENS COMMUNITY BOARD 1

Location:

Asset Location Comments: ON

40 FROM 37TH AV BARNETT AV/37TH AV

ON

40 FROM 37TH AV BARNETT AV/37TH AV

Initiated By:

4377

MARINELLI, JOSEPH

Initiated: 04-19-2018 11:00 AM

Scheduled: N/A

Assigned To:

1916

CHARLES-RAMIREZ, JOSE

Service# 186549435

District: 844166960

Due: N/A

Authorization:

1177

ANELLO, THOMAS

Crew:

Maint Type:

Priority:

Problem:

Project:

Source:

Permit#

Completed: N/A

Out of Service: N

Potential Service Request: N

WO Responsibility:

WRQ

QUEENS REPAIRS

WO Comments:

Caller Comments for SR #: 186549435.....INSPECT AREA

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	04-19-2018	04-19-2018	4377- MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop. Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 9:37:03 AM



Report Date:Thursday, May 02, 2019

There are no user logs for this work order

Primary Caller Information

Primary Caller:

MARINELLI, JOSEPH

Address:

SUPERVISOR SQN

Day Phone:

(718)353-6904

Comments:

INSPECT AREA

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	04-19-2018	04-19-2018	4377-MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop. Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 8:44:33 AM

Activity Safety Messages:

There are no Safety Messages for this asset's Activity Code

Asset Safety Messages:



Non-Completed Work Order

Report Date: Thursday, May 02, 2019

Page 1 of 2

Work Order# **APPLY HOT PATCH** 844250902 **Activity: WA12I** Address: 37 AVE Pct: 114 Zip: 11101 48 ST Cross Street: **Borough: QUEENS** Compass Direction: N Block: Lot: CMBD: 401 Building ID: Unit ID: Qualifier: , Side Of , DIST: 1 FT, DIR: , Map# Sub-Area: Area: Location: 6X10 District: 844250902 Initiated By: 6255 FABLE, MOIRA LYN Initiated: 12-11-2018 07:44 PM Scheduled: N/A Assigned To: Service# 186549435 Due: N/A Authorization: Crew: Maint Type: Priority: Problem: Permit# Project: Completed: N/A Source: Out of Service: N Potential Service Request: N WO Responsibility: SQN SEWER MAINTENANCE-QUEENS N. WO Comments: 37 AVE AND 48 STSUPV MILLER / CEW CIVITANO/WYATT/WAGNER R 904/922/551 BACKHOE JOHNNYAO/L, SET UP W/Z. B/O 6X10 OVER SEWER BREAK 1' DOWN. FOUND ELECTRIC DUCTS RUNNING DIAGANALLY THROUGH EXCAVATION, DUG DOWN BY HAND AND EXPOSED CONNECTION. MIXED 2 BAGS OF CEMENT AND INSTALLED 12' OF PIPE W/3 COLLARS. B/F, TAMPED AND BLACKTOPPED Caller Comments for SR #: 186549435.....INSPECT AREA **Work Order Log History** Log Type Log Started Log Ended Comments Log By

There are no user logs for this work order

Primary Caller Information				
Primary Caller:	MARINELLI, JOSEPH	Call Date: 04-20-2018 08:11 AM		
Address:	SUPERVISOR SQN			
Day Phone:	(718)353-6904			
Comments:	INSPECT AREA			





Report Date: Thursday, May 02, 2019

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	04-19-2018	04-19-2018	4377-MARINELLI, JOSEPH	Marinelli/Salerni veh#334/563Tag#431602 install hood & hanger three courses brickwork unit ok no parking restriction Tag#431601 Sa25 connection broken verified with pole camera from basin to 10' out from basin. Basin 2ft. deep manhole 7' deep total distance 40' no parking restriction. Tag#431606 Sa22 install hood & hangar no parking bus stop Inspection down with P. Saurin (engineer). Input By: LINDA BUSH on 7/3/2018 8:44:33 AM

Activity Safety Messages:

There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: